

76940X Dumps

Avaya Converged Platform Support Exam

<https://www.certleader.com/76940X-dumps.html>



NEW QUESTION 1

A support engineer has completed the upgrade of a PodFX 3.1 system to ACP 4200 4.0.

What should the engineer do with Virtual Machine snapshots that were created during the upgrade process?

- A. The VM snapshots should be backed up to external storage and deleted immediately.
- B. The VM snapshots should be deleted immediately.
- C. The VM snapshots should be deleted within 72 hours of the verified, successful completion of the upgrade process.
- D. The VM snapshots should be left as they are as a backup of the upgrade process.

Answer: C

NEW QUESTION 2

A support engineer is experiencing some difficulty correlating the error messages and logs from different systems in the ACP 4200.

What should the engineer do to fix this problem?

- A. Use the VMware integrated time server to supply time to all systems.
- B. Manually synchronize the time on all the ACP systems to a correct vCenter.
- C. Use the MSC NTP service tied to external NTP time servers to synchronize the time on all systems.
- D. The VSP switches have NTP servers built into them, and all other systems can use NTP to synchronize to them.

Answer: B

NEW QUESTION 3

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. In preparation for upgrading the HPE server firmware, the engineer notices that another colleague has already downloaded files.

Which two files should the engineer use? (Choose two.)

- A. hp-firmware-ilo4-2.60-1.1.i386.rpm
- B. bp-avaya-dl360g9-g10-ACP-4_0-New-only.iso
- C. SP99382.exe
- D. ACP_40_ilo4_261.bin

Answer: BD

NEW QUESTION 4

An ESXi Host server has been replaced due to a fault.

To provide for this replacement, which portion of the Lifecycle Workbook needs to be updated?

- A. Power Cord Wiring
- B. Serial Numbers
- C. Network Data
- D. Switch Wiring

Answer: B

NEW QUESTION 5

Before starting the vCenter Server Appliance from 6.0 to 6.5, which Cluster feature needs to be disabled?

- A. vSphere HA
- B. vSphere DRS
- C. vSphere vMotion
- D. vSphere HA heartbeat datastore

Answer: B

NEW QUESTION 6

A support engineer is planning to migrate to Avaya Orchestrator from POS Applications. What are three tasks required as part of setting up Orchestrator? (Choose three.)

- A. Add to Storage Array.
- B. Add to System Manager.
- C. Change the Web interface's orchestratoradmin password.
- D. Change the CLI's root and aoadmin password.
- E. Activate the License.

Answer: BCE

NEW QUESTION 7

A support engineer logs into the System Manager (SMGR) application on an ACP 4.0 system with the intention of checking VPFM warning messages for the VSP switch. The engineer is unable to see the VPFM link in SMGR.

What could be causing this Problem?

- A. The VPFM link was removed from SMGR as part of the upgrade of the system to ACP 4.0.
- B. The engineer's SMGR account has insufficient access privileges to launch VPFM.
- C. The VPFM link has been renamed as Orchestrator in ACP 4.0.

D. The engineer should connect to VPFM directly and not through SMGR.

Answer: B

NEW QUESTION 8

Which feature in Avaya Orchestrator allows a support engineer to select the management protocols and credentials of the equipment that is to be monitored within the ACP 4200?

- A. Monitoring Setup
- B. Orchestrator Security Center
- C. Device and Credentials Editor
- D. ACP Configuration Wizard

Answer: D

NEW QUESTION 9

As part of a routine weekly maintenance test for the ACP 4200, a support engineer has been instructed to verify that the VMotion VMKernels for all ESXi hosts are reachable from each other using pings. During the latest maintenance test, the engineer notices that some of the pings are failing. Which potential impact would this have on the ACP 4200?

- A. There will be no impact on the ESXi hosts, but the VSPs may reboot periodically.
- B. vMotion may not work as expected.
- C. The ESXi hosts may not be reachable from vCenter Server appliance.
- D. The ESXi hosts may reboot periodically.

Answer: C

NEW QUESTION 10

As an engineer working with the ACP 4200, you see that the backup plan in place for the virtual machines relies heavily on VMware snapshots. Which statement describes Avaya's position on using VMware snapshots for a backup solution?

- A. VMware snapshots are the most robust backup solution for the ACP 4200.
- B. VMware snapshots should never be used as a backup and recovery method.
- C. VMware snapshots should be stored off site to ensure business continuity.
- D. VMware snapshots should be stored on the ACP 4200 they are backing up.

Answer: B

NEW QUESTION 10

Which key consideration is critical when upgrading an application in your ACP 4200 system?

- A. Ensuring that the application server is able to contact <http://support.avaya.com>
- B. Validating the customer lifecycle workbook information and updating any undocumented changes that were made
- C. Ensuring that you have the latest VSP software installed
- D. Checking the IP Template for the application information and updating it with any changes made to the application

Answer: C

NEW QUESTION 12

Refer to the exhibit.

When a support engineer navigates to Orchestrator's Rack View of an ACP 4200 system, the engineer notices that the V1-V6 slots on the right of the diagram are not populated.

What could be causing this problem?

- A. V1-V6 are used to represent Virtual Machines which are not present in this particular system.
- B. V1-V6 are used to represent Vertical PDUs which are not present in this particular system.
- C. V1-V6 are used to represent G450 Media Modules which are not present in this particular system.
- D. V1-V6 are only used for ACP 100 systems.

Answer: A

NEW QUESTION 14

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. The system has two pairs of ServerTech PDUs. Which statement about the PDU firmware file describes the upgrade process that the engineer needs to follow?

- A. It will need to be uploaded to all 4 PDUs.
- B. It will need to be uploaded to each PDU Management Web Interface.
- C. It will need to be uploaded to one PD
- D. This PDU will then distribute the file to the remaining 3 PDUs.
- E. It will need to be uploaded to Orchestrato
- F. Orchestrator will then distribute the file to the 4 PDUs.

Answer: C

NEW QUESTION 15

Before downloading and applying a PDU patch, you must determine the type of PDU the ACP 4200 is using. Which two kinds of PDUs are valid? (Choose two.)

- A. Switched
- B. Synchronized
- C. Smart
- D. Stationary
- E. Static

Answer: BD

NEW QUESTION 18

Which equipment is standard in a new ACP 4200 4.0?

- A. IP 7254
- B. VSP 4850
- C. IP 8284
- D. VSP 7024

Answer: B

NEW QUESTION 19

What would a support engineer expect to find when using MSC to support, troubleshoot and maintain the ACP 4200 4.0?

- A. All current and previous license files
- B. Software library store
- C. Pod Upgrade Manager (PUM)
- D. VMware vSphere client application for VMware 6.5

Answer: D

NEW QUESTION 24

A support engineer logs into Avaya Orchestrator and clicks on the Service Availability icon for the Power Supply of a G450 device. What information is the engineer looking for?

- A. The current state of the power supply (OK, Warning, Unknown or Critical).
- B. The amount power (in Watts) that the power supply is using.
- C. A percentage breakdown of the state of the power supply (OK, Warning, Unknown or Critical) over a period of time.
- D. A list of other services that are available for the G450 device.

Answer: A

NEW QUESTION 26

A junior support engineer has been told by the support manager that summary status information for the ACP 4200 can be found in the Dashlets. Where would the engineer go to view this information?

- A. Login to Avaya Orchestrator's ACP Configuration Wizard link.
- B. Login to Avaya Orchestrator's Homepage.
- C. Login to the Management Server Console's Desktop.
- D. Login to the Management Server Console's ACP Configuration Wizard link.

Answer: B

NEW QUESTION 27

What does it mean when a support engineer clicks on the Latest Alerts link in Orchestrator and finds that there are no alerts listed?

- A. There are no Hosts or Services that have been in Warning or Critical state in the past 7 days.
- B. There are no Hosts or Services that have been in Warning or Critical state in the past 24 hours.
- C. There are no Hosts or Services that have been in Warning or Critical state in the past 4 hours.
- D. There are no Hosts or Services that are currently in Warning or Critical state.

Answer: D

NEW QUESTION 31

To view a graphical representation of the ACP 4200 and its individual components, where would a support engineer navigate?

- A. System Manager > Inventory
- B. Pod Visualization Manager > Home Dashboard
- C. Servertech PDU Web Interface > Equipment View
- D. Avaya Orchestrator > Rack Dashboard

Answer: B

NEW QUESTION 36

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0, and is upgrading the Extreme Network VSP switches to release 7.1. Which two applications available on the on the MSC would the engineer typically use for the upgrade process? (Choose two.)

- A. Avaya Orchestrator
- B. PuTTY
- C. WinSCP
- D. Enterprise Device Manager

Answer: AD

NEW QUESTION 40

Which benefit does the available G450 Gateway provide to the ACP 4200 solution?

- A. IP to H.323 translation
- B. SIP to IP transition
- C. IP to POTS transition
- D. SIP to SIP negotiation

Answer: B

NEW QUESTION 45

A maintenance window had been scheduled to allow for the upgrade of the firmware of one of the VSP switches in the ACP. However, steps were not taken to avoid receiving unnecessary notifications during this period. As a result, when the upgrade process started the VSP switch shows multiple critical alerts. At this point, what would a support engineer do to reduce the amount of these unwanted alerts?

- A. Use the Post-Event Downtime feature in Orchestrator.
- B. Use the Mass Acknowledgments feature in Orchestrator.
- C. Use the Recurring Downtime feature in Orchestrator.
- D. The engineer will have to wait for the upgrade process to complete.

Answer: B

NEW QUESTION 50

As part of the upgrade of a PodFX 3.1 system to ACP 4200 4.0, a support engineer is tasked with upgrading the ESXi hosts to VMware ESXi 6.5. Where would the engineer obtain the necessary upgrade files?

- A. From the Avaya support website
- B. From the VMware support website
- C. From the ACP 4.0 Upgrade DVD media
- D. From the HP support website

Answer: C

NEW QUESTION 55

While configuring the MSC to use NTP you see the NTP synching fail. What is the most common cause of this problem?

- A. VMware is not supporting NTP.
- B. The VSPs are rejecting the NTP messages.
- C. The NTP server is installed outside of the ACP 4200.
- D. The customer has a firewall between the MSC and the customer's NTP server.

Answer: B

NEW QUESTION 58

A support engineer is assigned to provide maintenance services for an ACP 4200 4.0 system. Which type of organization could the engineer expect to be assigned to?

- A. Small Business services
- B. Service Providers
- C. Large Enterprises
- D. Large Enterprises & Service Providers

Answer: C

NEW QUESTION 61

To use the Management Server Console (MSC) as their time source, how would the engineer configure the ESXi hosts?

- A. Login to the MSC, run the time_configuration.bat script.
- B. Login to the MSC, set Services > Time configuration > NTP Clients = IP addresses of the ESXi hosts.
- C. Login to the ESXi Hosts using the CLI, run the time_configuration.sh script.
- D. Login to vCenter server using the Web UI, set host > manage > Time configuration = IP address of the MSC.

Answer: B

NEW QUESTION 62

.....

Thank You for Trying Our Product

* 100% Pass or Money Back

All our products come with a 90-day Money Back Guarantee.

* One year free update

You can enjoy free update one year. 24x7 online support.

* Trusted by Millions

We currently serve more than 30,000,000 customers.

* Shop Securely

All transactions are protected by VeriSign!

100% Pass Your 76940X Exam with Our Prep Materials Via below:

<https://www.certleader.com/76940X-dumps.html>